

| REFERENCIA | REEMPLAZO | FABRICANTE |
|-----------------------|---|------------|
| H8151AF | | Sharp |
| HOP-120X | | Hitachi |
| HOP-1200S | DVD | Hitachi |
| HOP-1200S / mech | DVD | Hitachi |
| HOP-1200W | DVD | Hitachi |
| HPD-60 | DVD de Auto | Sharp |
| KHM-310AHC / mech | | Sony |
| KHM-313AHC / mech | | Sony |
| KHM-313AAM / mech | | Sony |
| KHS-313A | KHM-313AAA,KHS-310A | Sony |
| KHS-400C | KHS-400B | Sony |
| KHS-420AAA / mech | Playstation PSP | Sony |
| KHS-420BAA / mech | Playstation PSP | Sony |
| KSS-210B | KSS150B | Sony |
| KSS-212B | | Sony |
| KSS-213B / mech | 8-848-415-05 | Sony |
| KSS-213C | 8-820-018-02 | Sony |
| KSS-213C / mech | KSS-213Q | Sony |
| KSS-213CJ / mech | 8-820-003-08 | Sony |
| KSS-213D / mech | 8-820-131-01 | Sony |
| KSS-213V / mech | KSS-213C | Sony |
| KSS-215D / mech | KSS-213C,213R,215C / mech | Sony |
| KSS-215C / mech | KSS-213C,213R,215D / mech | Sony |
| RAE0150Z / con IC ☐ | RAE0152Z | Matsushita |
| RAE0152Z / con IC ☐ | RAE0150Z | Matsushita |
| RAF-3350 | Para Wii | Matsushita |
| SF-91(5/8)C | | Sanyo |
| SF-HD60 | DVD | Sanyo |
| SF-HD62 | DVD | Sanyo |
| SF-HD63 | XBOX360 | Sanyo |
| SF-HD65 | DVD | Sanyo |
| SF-HD850 / mech | SF-HD860 | Sanyo |
| SF-P100S(13P) / small | | Sanyo |
| SOH-AAV / mech | | Samsung |
| SOH-AD5 / mech | CMS-D77SG6F | Samsung |
| SOH-APU | SOH-AD3,SOH-ADU,SOH-AP | Samsung |
| SOH-DL3CH | CMS-S75RB | Samsung |
| SOH-DL6 | | Samsung |