

REFERENCIA	REEMPLAZO	FABRICANTE
1-526-990-11	F27	China
CTR-S80		China
F05U		China
F11 / GZS10-2-DD1		China
F12		China
F12A		China
F21		China
F25		China
F26		China
<b>F27</b>	69-0925 / 69-0208 / 69-0125	<b>Original</b>
F28		China
F34		China
F39		China
F40		China
F41		China
F43		China
F46	GZS10-4-BC	China
<b>F47</b>		Sony
GZS8-17		China
GZS8-6-1		China
GZS8-6-2		China
GZS8-6-3		China
GZS8-6-4		China
GZS8-6-402	GZS8-6-BD1	China
GZS8-6-5		China
GZS8-6-6		China
GZS8-6-7		China
GZS8-6-8		China
GZS8-6-9		China
GZS10-2-1		China
GZS10-2-101		China
GZS10-2-102		China
GZS10-2-103		China
GZS10-2-104		China
GZS10-2-105	GZS10-2-DD1 , HPS0520-24	China
GZS10-2-106		China
GZS10-2-107	Sin Cable	China
GZS10-2-107B	Con Cable	China
GZS10-2-108		China
GZS10-2-109		China
GZS10-2-2		China
GZS10-2-3		China
GZS10-2-4	HPS2171-7	China
GZS10-2-402		China
GZS10-2-5		China
GZS10-2-6		China
GZS10-2-7		China
GZS10-2-BD	F10, F12Y	China
GZS10-3-1	F08	China
GZS10-4-BC	F46	China
GZS12-4-2	F09	China

<b>HPS0680-2</b>		Sony
PA219		China